

FITNESS CERTIFICATE

(To be filled by the Inspecting Officer Assistant Engineer)

1. Name of the Officer : Dileep . L
2. Name of the School : M.A.M Bethany Public School, Kumily
3. Location with name of Education District/ Sub District : Kattappana / Peermedu
4. Classification of Building as specified in column 4 : GF-36.45 X 8.65
of the application for fitness certificate and size FF-36.45 X 8.65m-Mar Athanasios Block
GF- 403.00 m² 41.07X 9.45X 35
FF- 403.00m² Mar Ivanios Block Office
5. Period for which the Certificate is issued : 2023-2024
6. Nature of defects, if any
- a. Foundation and basement : NIL
- b. Superstructure : NIL
- c. Doors and windows : NIL
- d. Wood work wrought and put up : NIL
- e. Roof : NIL
- f. Flooring : NIL
- g. Miscellaneous (Cracks etc.) : NIL
7. Any major defects notified which will render the building unsafe in any manner : NIL
8. Whether maintenance work have been done properly : Yes
9. Whether the structure is sound or not for conducting classes : Sound under normal weather condition

Note: 1 The stability of the structure should be examined also with reference to location , altitude, intensity of wind, exposure to flood etc.

2 Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.

CERTIFICATE

Certified that the school building was inspected by me on 17-05-2023 and found to be fit/ unfit to conduct classes, for the period 2023-2024 for the reasons stated above.

Place: Kumily

Date: 17.05.2023
Manager

M.A.M Bethany Public School
Kumily - 685509



Sa. Seema
Principal
M.A.M. Bethany Public School
Kumily

(Seal) *[Signature]*
Assistant Engineer
Dileep L, PEN: 611199
Assistant Engineer,
LSGD (LID & EW)
Kumily Grama Panchayath